


MOD WORKSTATION CONTROLS



EFFECT TYPE:
Overdrive, Distortion, Boost, Tremolo, Auto Filter, Phaser, Chorus, Flanger, Rotary

Power Requirement:
9VDC Center Negative, 118mA+
Power Supply Required.

Input/Output:
Mono Instrument In,
Mono Instrument Output

